FROCESSING COPY

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

		S-Hi-C-R-H-F			25X1
COUNTRY	East Germany		REPORT		
SUBJECT	Gross Doelln Airfield		DATE DISTR.	10 January 195	7
			NO. PAGES	1	
			REQUIREMENT NO.	RD	
DATE OF INFO.			REFERENCES		25 X 1
PLACE & DATE ACQ.					
	SOURCE EVALUATIONS	ARE DEFINITIVE. APPRA	ISAL OF CONTEN	T IS TENTATIVE	
	airfield which gives in Count, (2) Aircraft Det and Radar, (6) Aircraft No. 1 Storage Installat aerial arrays is also i	ails, (3) Flying A Construction, (7) ion. A sketch whi	e following he ctivity, (4) N	Movements, (5) Ra	craft dio
					25 X 1

77

. 25X1

S-E-C-R-E-T

STATE ARMY X NAVY X AIR X FBI AEC

[Note: Washington distribution indicated by "X"; Field distribution by "#".)

EAST GERMANY	
AIR/MILITARY	
GROSS DOELLN Airfield Order of Battle	25X1
APPENDIX	
Attached at Appendix "A" is a series of rough sketche	
details of newly erected aerial arrays observed on GROSS DOELLN	airfield.
1. AIRCRAFT COUNT	25X1
33 Frescos, including 21 Fresco N's.7 Farmers2 Cabs1 Flashlight.	
2. AIRCRAIT DETAILS	
(i) Flashlight	25X1
(ii) Fresco D's	
(iii) Remaining Frescos,	
(iv) Farmers	
(v) Cabs	
b) Aircraft finish:	
(i) Farmers - bright silver grey.	
(ii) Frescos - dull silver grey.	
(iii) Flashlight - Overall matt medium grey.	
(iv) Cabs - matt olive green.	
c) Fittings:	
(i) Frescos - All Frescos observed on the airfield were fitted with underslung auxiliary wing tanks, fit at the rear.	
(ii) All positively identified Fresco D's observed the dispersal area were fitted with SCAN ODD radars. the Fresco D's were f ventral shallow type radome. It was impossible to a dispersal area whether the other aircraft were fitted equipment.	At least 4 of itted with a 25X1 scertain in the
(iii) Farmers - All Farmers were fitted with large u cigar-shaped drop tanks with vanes at the rear.	nderslung
(iv) Flashlight - This aircraft remained parked in bunch of Frescos, and it was only possible to obtain of the aircraft. The bulbous nose appeared to be "s all one piece, and not broken up into a series of win	a limited sight olid" and was

25X1

- 2 -

aircraft was observed on the seeing of a similar type,	airfield on two occasions, this			
under the belly of the aircra	were to be seen, both being located ft. The guns were of equal calibre prox. 35 - 40 mm. diameter (by comparison under the nose of the nearby (Frescos).			
d) <u>Dispersal:</u>				
(i) On the day of observation the SOUTH EASTERN corner of the				
(ii) No aircraft were parked adjoining the take-off ends of	25X d on either of the readiness platforms f the runway.			
still appeared to be in a sta- cluster of accommodation care	ion, the entire aircraft dispersal area te of readiness. The 25X wans and workshops vehicles remained in covered, although no aircrew were to be			
3. FLYING ACTIVITY				
No unusual flying activity has	s been observed			
and discharge small parties of personne	25X 2's wore observed to land at the airfield 1, later identified as being Russian ORs al proceeded to the main AA site adjoining			
4. MOVEMENTS				
No significant movements have blocks and married quarters on the airfi there were no signs of packing, or asser rail head to indicate any pending movement	ield appear to be fully occupied, and abling of equipment near the airfield			
5. RADIO AND RADAR				
(i) Order of Battle:				
were in situ:	the following radio and radar equipments			
a) The TOKEN	25X			
b) A CROSSFORK and a FISHNET				
c) A KNIFEREST and FISHNET, to	gether with 2 radio vans			
d) A FISHNET, a CROSSFORK and the immediate vicinity of t	a WHIFF type radar in the heavy AA site			
	beacons located in the EASTERN approach and the inner marker beacon was occupied			
	the multi-radar site located in permanent signals installations have 25X			

- 3 -

(ii) New reflector type shields 25X1 900 metres WEST of the EASTERN end of the main EAST/WEST runway and approximately 10 metres from its NORTHERN edge, a new metal shield has been set up surmounting a 2 metre high mast. This shield is triangular in shape] its pointed side facing EAST (see sketch (a) of Appendix "A"). 25X1 The raised surface has 3 distinct portions, the outer and inner bands being black finished, whilst the strip contained between them was a bright silver colour. An identical shield is located in a corresponding 25X1 position 10 metres SOUTH of the SOUTHERN parallel taxiway. There are no visible cable connections leading up to either of these reflectors. (iii) Spherical mesh array surmounting Building 24: A wire mesh spheroid, having a diameter of approximately ½ metre has been set up on a short mast on the roof of Building 24, located in Jagen 122 (see sketch (b) of Appendix "A"). 6. AIRFIELD CONSTRUCTION a) Concrete apron in Jagen 196 No developments whatsoever have taken place on the previously reported hollow "hangar" type building adjoining the SOUTHERN side of the concrete apron in Jagen 196. A recent inspection of this area confirmed the facts that it is of an unusually heavy construction, having shallow walls approximately 60 - 70 cm. in height made of reinforced concrete approx. 50 cm. in thickness. There were no signs of any gaps being left in the wall for the subsequent insertion of metal frames, and the general finish of the walls would tend to indicate that they are complete, and not intended for further development. The open side (NORTHERN) which immediately adjoins the concrete apron has a width of approx. 20 metres (judged by counting number of concrete squares on the apron). There is a short wall approx. 3 - 4 metres in length, adjoining this gap, and then the side walls proceed SOUTHwards for a distance of approx. 15 - 18 metres. floor contained within the walls is covered with a The 25X1 layer of sand of unknown thickness, so that no under concrete base is visible. No holes could be ascertained in the floor, and during its initial construction no deep excavation was noted which would indicate the presence of any type of basement. The lower wall of this building is located approx. 10 metres NORTH of the main airfield rail spur. b) MT 25X1 A provisional MT/ has been set up adjoining the EASTERN side of the new concrete road which is contained between 25X1 Jagens 159 and 160. This roadway has a width of approx. $5\frac{1}{2}$ metres and links the air traffic control tower to the concrete roadway connecting the main domestic site to the underground generator station (Building VIII 25X1 pumps fed from comprises 2 provisional This / a series of large metal drums each approx. 1 metre in length with a diameter 25X1 of approx. 40 - 50 cm. The only permanent buildings on the site consist of a brick shed and a nearby concrete apron, and the entire site is enclosed by a low barbed wire fence. 7. MISCELLANEOUS 25X1

b) No. 1 Storage Installation located in Jagens 115 and 116 remains

Sanitized Copy Approved for Release 2010/02/16 : CIA-RDP80T00246A032100170001-6

25X1

- 4 -


empty, and was only lightly guarded. No vehicles or trains have been observed using this depot.


25X1



APPENDIX "A"

Multi Radar Site Jagens Sik • 217





(a)
Metal Shieldo
adjoining runus
and taxiwan at

(b)

wire Shhereid

set the on roof

of Building Ety.

25X1

GROSS DOFLLM AIRFIELD





Sanitized Copy Approved for Release 2010/02/16: CIA-RDP80T00246A032100170001-6